

Vauxhall Zafira Service Info

Whilst a 16-pin connector was present on some Vauxhall cars before January 2001, it appears that they did not support EOBD / OBDII diagnostics until January 2001. The wiring of the earlier connector does not appear to be EOBD / OBDII compliant.

Service Light Reset

Vauxhall 1999 onwards

- Turn Ignition Off
- Hold Trip Reset In
- Turn Ignition On
- Still Holding Trip Reset wait for three dashes
- Turn off Ignition
- Turn on Ignition to confirm

Helpful web sites

www.gendan.co.uk/diagnostic

www.onboarddiagnostics.co.uk/index.html

www.omitec.com

www.rontronics.com

www.cryptontechnology.com

www.hiltoncanine.com

www.aeswave.com